


3.2 Modification

Cut the left tab as is indicated the following picture



3.3 Connection

Connection in the VF5+ according to label.

